Notice

TSP Name:Gulf South Pipeline Company, LLCTSP:78444247Category:Critical / Planned Service OutagePost Date/Time:03/14/202403:58:05PMNotice Type Desc:MaintenanceNotice Effective Date/Time:10/01/202409:00:00AMNotice Stat Desc:InitiateNotice End Date/Time:10/12/202409:00:00 AMNotice ID:5034794Response Date/Time:VPrior Notice:Vor response requiredY

Subject: Bistineau Compressor & Storage Field Maintenance

Notice Text: Gulf South will be performing maintenance on Bistineau Compressor & Storage Field.

Nominations utilizing the Bistineau storage facility during this maintenance will be scheduled to the extent that Gulf South is able to utilize its other facilities to balance the system.

Imbalance payback to Gulf South will require authorization by Gulf South and will be approved dependent upon the ability to manage imbalance payback to Gulf South with imbalance payback from Gulf South.

Anticipated impact to all services including Primary Firm.

Please contact your customer service representative with any questions.